REMARKS

Upon further review of the above identified case, Applicant noted that Figure 1 does not correctly show annular groove 2k. Annular groove 2k is currently shown in the lower half of Figure 1, but is not shown in the upper half of Figure 1. As shown in Figure 2, groove 2k is annular and, thus, forms a groove completely around the outer circumference of outer ring.

Figure 1 has been amended to correctly show annular groove 2k in the upper half as well as the lower half of Figure 1. A replacement drawing sheet has been attached which shows the change to Figure 1.

Respectfully submitted,

LUCAS & MERCANTI, LLP

v: Donald Ci

Donald C. Lucas, Reg. No. 31,275

Attorney for Applicant(s)

475 Park Avenue South, 15th Floor

New York, New York 10016

Tel. 212-661-8000 Fax (212) 661-8002

DCL/JRW/ns